

## Quick method for measuring the humidity of all plastic materials



- Possibility of connecting to a computer
  - Simple and practical procedure with the sample
    - Short measurement time
    - 6 automatic programs
  - Reading accuracy of 10 ppm (0.01%)
- 20 methods that can be stored in memory