

Quick method for measuring the humidity of all plastic materials



- Possibility of connecting to a computer
- Simple and practical procedure with the sample
- Short measurement time
- 6 automatic programs
- Reading accuracy of 10 ppm (0.001%)
- 20 methods that can be stored in memory